

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 27

Township: 10 North


Range: 2 West

Corner ID: BeBl O-19

Monument Description & Remarks: 5/8" Rebar with cap, "MUNDY L.S.880014". Survey Sign 2.5ft above ground at pt. B

References On File: Michael D. Mundy survey, William & Marilyn Aynes (1996), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 42 Page No. 54




- A - 5/8" Rebar with cap
- B - S 02° W 0.20' to Survey Sign on metal fence post
- C - N 82° W 18.68' to MAG nail in 10" power line pole
- D - N 14° W 37.87' to 1½" Iron Pipe 6" above ground
- E - S 64° E 34.96' to 3/4" Iron Pipe 4" below ground

Not To Scale
Compass Bearing Magnetic North



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 15th day of May, 2009.

Kevin P. Enright



Administered by the Monroe County Surveyor Review Board

Date: 6-16-09 DB



Be Bl O-19

05/15/2009